



Republic of the Philippines
PROVINCE OF ISABELA

COMPOUND MAINTENANCE OFFICE

ACCOMPLISHMENT REPORT CY-2022

The Provincial Government of Isabela (PGI), by virtue of the Local Autonomy through the Sangguniang Panlalawigan has promulgated Ordinance # 05, s-2013 to ensure public safety, promote peace and order and further strengthen the capability of the PGI towards the effective delivery of basic services to the inhabitants through its highly efficient and competent employees/public servants. Towards this end, the province is committed to ensure occupational health and safety of the PG for personnel welfare and development.

The Compound Maintenance Office (CMO) directs overall management and maintenance of the Provincial Capitol compound/grounds including man-made and natural features and facilities situated therein.

Repairs and maintenance of buildings owned and operated by the Provincial Government and all its facilities and other maintenance and rehabilitation or construction activities are being undertaken by carpenters, painter and electrician.

In accordance with the activities and processes of the CMO to ensure a suitable environment necessary for the operations of the PGI staffs assigned for the maintenance and orderliness of Capitol Compound rendered 260 days of service in 2022.

COMPOUND MAINTENANCE IN ACTION

Routine Maintenance







Minor Repairs/fabrication/Construction/Maintenance

Replacement of fluorescent lamp



Cleaning of Air-conditioner



Plastering of wall



construction of Animal shelter



Assigned in the on-going rehabilitation of the Vice-President's satellite office



Animal Shelter



Preparation of stage for PGI program



Fabrication of Cabinet



Installation of Fabricated steel gate/ barbed wires and application of rust Proofing for steel tank perimeter fence



wall plastering



Fabrication of Cabinet for Isabela Tourism Office



Fabrication of plat form




Room rehabilitation



Repair/construction of Paskuhan Village



Preparation/Construction of Giant Christmas Lantern



construction of x-ray room at Manuel A. Roxas District Hospital



Transportation of materials for the repair
Of school building



Fabrication of Cabinet dorm for School
for the deaf



Repair & preparation of stage for oath
Taking of newly elected official



Preparation of Stage



Construction of Septic Tank



Multi-Purpose Evacuation Center, Water
Refilling Station, Administration Building
(PH.2) & Drilling/Installation of Water System
w/Submersible Pump.



Submitted by:


REUBEN COTURINGAN
Compound Maintenance Officer